



## Power on/off

To set auto-power off time: press and then press and hold for 2 seconds. Now press [MODE] button to cycle between 0, 60, 120 or 180 seconds timeout. Press to save. Screen will display "Pass".



## Tare

Reset weight to zero.

[MODE]

## Change weighing units

Cycle between grams (g), carats (ct), denarius weight (dwt), troy ounces (ozt), ounces (oz), grains (gn).

[PCS]

## Count pieces using a reference weight

To count: press to turn scale on. Put items on scale. Press [PCS] once to display the number of items.

To reset the reference weight: press to turn scale on. Put items on scale. Press [PCS] once. Press and hold [PCS] for 2 seconds. PCS will flash on top left of display. Press the [MODE] button to select the quantity of items (25, 50, 60, 75, 100) on the scale. Press [PCS] to save.

## Specifications

Capacity: 2000g with 0.1g accuracy

Power: 2x AAA batteries

Warranty: This product is covered by a one year warranty, which does not include the following: (1) fall, shock, over weight or other improper use. (2) damage due to fire, earthquakes, floods, storms, lightning and other natural disasters. (3) usage contrary to the indications of this manual. Stains, scratches, or discoloration may happen with use: this is normal.

Use: This product is made for home use only.  
Not approved for commercial use.

For help: <http://decentespresso.com/scale>  
[support@decentespresso.com](mailto:support@decentespresso.com)

